

PQP, PQE

Технические характеристики

По вопросам продаж и поддержки обращайтесь:

Алматы (7273)495-231	Казань (843)206-01-48	Новокузнецк (3843)20-46-81	Смоленск (4812)29-41-54
Архангельск (8182)63-90-72	Калининград (4012)72-03-81	Новосибирск (383)227-86-73	Сочи (862)225-72-31
Астрахань (8512)99-46-04	Калуга (4842)92-23-67	Омск (3812)21-46-40	Ставрополь (8652)20-65-13
Барнаул (3852)73-04-60	Кемерово (3842)65-04-62	Орел (4862)44-53-42	Сургут (3462)77-98-35
Белгород (4722)40-23-64	Киров (8332)68-02-04	Оренбург (3532)37-68-04	Тверь (4822)63-31-35
Брянск (4832)59-03-52	Краснодар (861)203-40-90	Пенза (8412)22-31-16	Томск (3822)98-41-53
Владивосток (423)249-28-31	Красноярск (391)204-63-61	Пермь (342)205-81-47	Тула (4872)74-02-29
Волгоград (844)278-03-48	Курск (4712)77-13-04	Ростов-на-Дону (863)308-18-15	Тюмень (3452)66-21-18
Вологда (8172)26-41-59	Липецк (4742)52-20-81	Рязань (4912)46-61-64	Ульяновск (8422)24-23-59
Воронеж (473)204-51-73	Магнитогорск (3519)55-03-13	Самара (846)206-03-16	Уфа (347)229-48-12
Екатеринбург (343)384-55-89	Москва (495)268-04-70	Санкт-Петербург (812)309-46-40	Хабаровск (4212)92-98-04
Иваново (4932)77-34-06	Мурманск (8152)59-64-93	Саратов (845)249-38-78	Челябинск (351)202-03-61
Ижевск (3412)26-03-58	Набережные Челны (8552)20-53-41	Севастополь (8692)22-31-93	Череповец (8202)49-02-64
Иркутск (395)279-98-46	Нижний Новгород (831)429-08-12	Симферополь (3652)67-13-56	Ярославль (4852)69-52-93
Россия (495)268-04-70	Киргизия (996)312-96-26-47	Казахстан (7172)727-132	

QUARTZ CONTROL PLATES – FOR A STEADILY HIGH MEASUREMENT ACCURACY

Like all measurement devices, polarimeters should be calibrated and adjusted on a regular basis. Sugar solutions are widely used as a standard for this purpose. Their disadvantage: They always have to be freshly produced for measurements. User errors during the initial weighing are difficult to prevent, and the high temperature dependency of the respective solutions also needs to be taken into account. Optically active quartz is better suited for the calibration and adjustment of polarimeters, which is cut from mono-crystals and installed in stainless steel casings.

We offer you a selection of PTB-certified, OIML-, ICUMSA- and pharmacopoeia-compliant premium quartz control plates. For applications that do not require a PTB certification and where a PTB-traceable factory certificate is sufficient, we can provide the corresponding more inexpensive versions. The following applies to both of our quartz control plate versions: They are highly accurate and last for an indefinite period of time compared to calibration fluids used with other measurement devices. However, they should also be calibrated on a regular basis.



P3000 with premium quartz control plate

PREMIUM QUARTZ CONTROL PLATES WITH PTB CERTIFICATE

	PQP+17	PQP+34	PQP-17	PQP-34
TYPE	Polarimeter Quartz Professional (PQP)			
ACCURACY	±0.001°			
ANGLE OF ROTATION	+17° (±1°), +50 °Z (±1 °Z)	+34° (±1°), +99 °Z (±1 °Z)	-17° (±1°), -50 °Z (±1 °Z)	-34° (±1°), -99 °Z (±1 °Z)
WAVELENGTH	589 nm			
TEMPERATURE	20 °C			
HOUSING	Stainless steel			
SUITABLE FOR	P8000 series and P3000			

SIMPLE QUARTZ CONTROL PLATES WITH FACTORY CERTIFICATE, TRACEABLE TO PTB CERTIFICATE

	PQE+17	PQE+34	PQE-17	PQE-34
TYPE	Polarimeter Quartz Economy (PQE)			
ACCURACY	±0.005°			
ANGLE OF ROTATION	+17° (±1°), +50 °Z (±1 °Z)	+34° (±1°), +99 °Z (±1 °Z)	-17° (±1°), -50 °Z (±1 °Z)	-34° (±1°), -99 °Z (±1 °Z)
WAVELENGTH	589 nm			
TEMPERATURE	20 °C			
HOUSING	Stainless steel			
SUITABLE FOR	P3000, limited suitability for P8000			

По вопросам продаж и поддержки обращайтесь:

Алматы (7273)495-231	Казань (843)206-01-48	Новокузнецк (3843)20-46-81	Смоленск (4812)29-41-54
Архангельск (8182)63-90-72	Калининград (4012)72-03-81	Новосибирск (383)227-86-73	Сочи (862)225-72-31
Астрахань (8512)99-46-04	Калуга (4842)92-23-67	Омск (3812)21-46-40	Ставрополь (8652)20-65-13
Барнаул (3852)73-04-60	Кемерово (3842)65-04-62	Орел (4862)44-53-42	Сургут (3462)77-98-35
Белгород (4722)40-23-64	Киров (8332)68-02-04	Оренбург (3532)37-68-04	Тверь (4822)63-31-35
Брянск (4832)59-03-52	Краснодар (861)203-40-90	Пенза (8412)22-31-16	Томск (3822)98-41-53
Владивосток (423)249-28-31	Красноярск (391)204-63-61	Пермь (342)205-81-47	Тула (4872)74-02-29
Волгоград (844)278-03-48	Курск (4712)77-13-04	Ростов-на-Дону (863)308-18-15	Тюмень (3452)66-21-18
Вологда (8172)26-41-59	Липецк (4742)52-20-81	Рязань (4912)46-61-64	Ульяновск (8422)24-23-59
Воронеж (473)204-51-73	Магнитогорск (3519)55-03-13	Самара (846)206-03-16	Уфа (347)229-48-12
Екатеринбург (343)384-55-89	Москва (495)268-04-70	Санкт-Петербург (812)309-46-40	Хабаровск (4212)92-98-04
Иваново (4932)77-34-06	Мурманск (8152)59-64-93	Саратов (845)249-38-78	Челябинск (351)202-03-61
Ижевск (3412)26-03-58	Набережные Челны (8552)20-53-41	Севастополь (8692)22-31-93	Череповец (8202)49-02-64
Иркутск (395)279-98-46	Нижний Новгород (831)429-08-12	Симферополь (3652)67-13-56	Ярославль (4852)69-52-93
Россия (495)268-04-70	Киргизия (996)312-96-26-47	Казахстан (7172)727-132	